

# MATERIAL SAFETY DATA SHEET

12-96

Version Date 07/10/90

## KLEEN GREEN - NOZZLE GEL

Print Date 10/09/92

**SECTION 1**

PRODUCT IDENTIFICATION

COMPANY NAME WHO SENT MSDS  
 COMPANY ADDRESS  
 EMERGENCY PHONE NUMBER  
 MSDS VERSION NUMBER  
 TRADE NAME

THERMACOTE WELCO  
 1051 YORK ROAD  
 KINGS MOUNTAIN, NC 28086  
 (800)-424-9300  
 2  
 KLEEN GREEN - NOZZLE GEL

Wel 77

HAZARD RATING (HMIS)

HEALTH HAZARD - 0  
 FLAMMABILITY HAZARD - 1  
 REACTIVITY HAZARD - 3  
 PERSONAL PROTECTION - 0  
 0 - MINIMAL  
 1 - SLIGHT HAZARD  
 2 - MODERATE HAZARD  
 3 - SERIOUS HAZARD  
 4 - SEVERE HAZARD

HMIS DESIGNATION KEY

**SECTION 2**

HAZARDOUS COMPONENTS

MATERIAL	% BY WEIGHT	CAS NUMBER	ACGIH TLV (Mg/M3)	SEC 313
NONE	NA	NA	NA	NA

**SECTION 3**

PHYSICAL PROPERTIES

BOILING POINT  
 MELTING POINT  
 VAPOR PRESSURE  
 VAPOR DENSITY (AIR = 1)  
 SOLUBILITY IN WATER  
 SPECIFIC GRAVITY  
 EVAPORATION RATE  
 APPEARANCE AND ODOOR

NA  
 100.4-140F  
 NA  
 NA  
 NIL  
 .815-.88  
 NA  
 OPAQUE, NO ODOR

**SECTION 4**

FIRE AND EXPLOSION DATA

FLASH POINT  
 EXTINGUISHING MEDIA  
 SPECIAL PROCEDURES  
 UNUSUAL HAZARDS

GREATER THAN 390F (estm D-92)  
 CARBON DIOXIDE, DRY CHEMICAL, OR FOAM,  
 PRESSURE-DEMAND, SELF-CONTAINED PROTECTION SHOULD BE PROVIDED. WATER SPRAY  
 IS AN UNSUITABLE EXTINGUISHING AGENT.  
 NONE

**SECTION 5**

REACTIVITY DATA

STABILITY  
 CONDITIONS TO AVOID  
 HAZARDOUS POLYMERIZATION  
 CONDITIONS TO AVOID  
 INCOMPATIBILITY  
 HAZARDOUS DECOMPOSITION PRODUCTS

STABLE  
 NONE  
 WILL NOT OCCUR  
 NONE  
 NA  
 NA

**SECTION 6**

HEALTH HAZARD DATA

ROUTES OF ENTRY  
 HEALTH HAZARDS  
 CARCINOGENICITY  
 SIGNS & SYMPTOMS OF EXPOSURE  
 MEDICAL CONDITIONS FROM EXPOSURE  
 EMERGENCY & FIRST AID  
 ADDITIONAL INFORMATION

NONE  
 NONE  
 NA  
 NA  
 NONE  
 EYES: FLUSH EYES WITH WATER FOR 15 MINUTES. SKIN: WASH WITH SOAP AND WATER.  
 INHALATION: REMOVE TO FRESH AIR. CALL PHYSICIAN. INGESTION: DRINK WATER.

**SECTION 7**

PRECAUTIONS FOR SAFE HANDLING AND USE

SPILL AND LEAK PROCEDURES  
 WASTE AND DISPOSAL METHOD  
 HANDLING AND STORING PRECAUTIONS  
 OTHER PRECAUTIONS

SHUT OFF LEAK AND DIKE UP LARGE SPILLS. AFTER COOLING AND SOLIDIFICATION,  
 SCRAPE AND/OR SHOVEL UP MATERIAL. FINALLY, CLEAN AREA WITH AN OIL ABSORBENT  
 MATERIAL.  
 DISPOSE OF IN ACCORDANCE WITH LOCAL, STATE AND FEDERAL REGULATIONS.  
 STORE AWAY FROM FLAME, HEAT (250) MAXIMUM. ALSO KEEP AWAY FROM STRONG  
 OXIDIZING AGENTS.  
 NONE

**SECTION 8**

CONTROL MEASURES

RESPIRATORY MEASURES  
 VENTILATION  
 PROTECTIVE GLOVES  
 EYE PROTECTION  
 OTHER PROTECTIVE EQUIPMENT  
 WORK/HYGIENIC PRACTICES

NONE REQUIRED.  
 NA  
 IMPERVIOUS WHEN MOLTEN.  
 WEAR A FACE SHIELD IF PRODUCT IS MOLTEN  
 WHEN MOLTEN, WEAR COVERALLS.  
 NA

**SECTION 9**

DISCLAIMER

THIS DATA IS BELIEVED TO BE ACCURATE. THERMACOTE WELCO MAKES NO WARRANTY TO AND DISCLAIMS ALL LIABILITY FROM RELIANCE.

**SECTION 10**

ADDITIONAL INFORMATION

NEW JERSEY RIGHT TO KNOW INFORMATION: (HAZARDOUS & NON-HAZARDOUS) USP  
 PETROLATUM CAS # 8009-03-8 GREEN DYE CAS # 4851-50-7  
 NA = NOT APPLICABLE